




COMBI Xi



www.spitpaslode.com



NEVER STOP BUILDING




014749




BEST USE
BEFORE



= 1250 (-5°C°)



MAG1 +




Ø = 2.8 - 3.1 mm
L = 51 -> 90 mm (Smooth & Ring)
RoundDrive® 34°

MAG2 +



Ø = 4 mm
L = 35 / 40 / 50 mm (Hardened Ring
Nails)
34°





= 13 000 max





	15 min.	2 500 max.
	60 min.	10 000 max.
	90 min.	13 000 max.



25%	50%	75%	100%
☐	☐	☐	☒
☐	☐	☒	☒
☐	☒	☒	☒
☒	☒	☒	☒






0 -> 300	
	☐
	☐
	☐
	☒



014749



$-15^{\circ}\text{C} \leq T \leq +49^{\circ}\text{C}$ - 1000/hour - 2 nails/second















014749



$-15^{\circ}\text{C} \leq T \leq +49^{\circ}\text{C}$ - 1000/hour - 2 nails/second








014749



MAG1 +



Ø = 2.8 - 3.1 mm

L = 51 -> 90 mm (Smooth & Ring)

RounDrive® 34°





MAG2 +



Ø = 4 mm








L = 35 / 40 / 50 mm (Hardened Ring Nails)






34°





014749
















50 000



014749





RESET



>10s

Resting position / Ruheposition / Position de repos / Ruststand /
Posición de descanso / Posizione di riposo / Posição de descanso /
Pozycja spoczynku / Klidová poloha / Nyugalmi állapot / ПОЛОЖЕНИЕ
В нерабочем состоянии / Θέση αδράνειας / Hvilestilling / Viloläge
/ Hvileposisjon / Lepoasento / Položaj mirovanja / Pokojová poloha /
Položaj mirovanja/ وضع السكون / Ramybės padėtis / Ooteasend / Miera
stāvoklis / Hvíldarstaða







Route de Lyon F-26500
Bourg-lès-Valence
France