



# Oras Safira

Installation and maintenance guide








4-10



11-15



16



17-21





22



## 1030S



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.27 l/s (300 kPa)  
 160 kPa (0.2 l/s)  
 max. +80°C



[mpi.oras.com/1030S](http://mpi.oras.com/1030S)

## 1030FS, 1030FS-107



I (ISO 3822) Oras lab.  
 EN 817  
 50 - 1000 kPa  
 0.25 l/s (300 kPa)  
 0.116 l/s (300 kPa w/Controller)(-107)  
 195 kPa (0.2 l/s)  
 max. +70°C



[mpi.oras.com/1030FS](http://mpi.oras.com/1030FS)

## 1035S


I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.27 l/s (300 kPa)  
 160 kPa (0.2 l/s)  
 max. +80°C



[mpi.oras.com/1035S](http://mpi.oras.com/1035S)

## 1035FS


I (ISO 3822) Oras lab.  
 EN 817  
 50 - 1000 kPa  
 0.25 l/s (300 kPa)  
 195 kPa (0.2 l/s)  
 max. +70°C



[mpi.oras.com/1035FS](http://mpi.oras.com/1035FS)

## 1022S


I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.17 l/s (300 kPa)  
 100 kPa (0.1 l/s)  
 max. +80°C



[mpi.oras.com/1022S](http://mpi.oras.com/1022S)

## 1027S

I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.17 l/s (300 kPa)  
 100 kPa (0.1 l/s)  
 max. +80°C





[mpi.oras.com/1027S](http://mpi.oras.com/1027S)



## 1032F



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.16 l/s (300 kPa)  
 120 kPa (0.1 l/s)  
 max. +70°C



[mpi.oras.com/1032F](http://mpi.oras.com/1032F)

## 1038



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.27 l/s (300 kPa)  
 160 kPa (0.2 l/s)  
 max. +80°C



[mpi.oras.com/1038](http://mpi.oras.com/1038)

## 1038F, 1038F-104, 1038F-105



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.23 l/s (300 kPa)  
 0.054 l/s (300 kPa w/Controller)(-104)  
 0.06 l/s (300 kPa w/Controller)(-105)  
 240 kPa (0.2 l/s w/Reducer)(-104, -105)  
 240 kPa (0.2 l/s)  
 max. +70°C



[mpi.oras.com/1038F](http://mpi.oras.com/1038F)

## 1039



I (ISO 3822)  
EN 817  
50 - 1000 kPa  
0.27 l/s (300 kPa)  
160 kPa (0.2 l/s)  
max. +80°C



[mpi.oras.com/1039](http://mpi.oras.com/1039)

## 1039F



I (ISO 3822)  
EN 817  
50 - 1000 kPa  
0.23 l/s (300 kPa)  
240 kPa (0.2 l/s)  
max. +70°C



[mpi.oras.com/1039F](http://mpi.oras.com/1039F)

## 1057F

I (ISO 3822)  
EN 817  
50 - 1000 kPa  
0.23 l/s (300 kPa)  
240 kPa (0.2 l/s)  
max. +70°C





[mpi.oras.com/1057F](http://mpi.oras.com/1057F)



### 1033


I (ISO 3822)  
 EN 817, EN 1113  
 50 - 1000 kPa  
 0.16 l/s (300 kPa)  
 110 kPa (0.1 l/s)  
 max. +80°C



[mpi.oras.com/1033](http://mpi.oras.com/1033)

### 1034


I (ISO 3822)  
 EN 817, EN 1113  
 50 - 1000 kPa  
 0.16 l/s (300 kPa)  
 115 kPa (0.1 l/s)  
 max. +80°C



[mpi.oras.com/1034](http://mpi.oras.com/1034)

### 1034F

I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.14 l/s (300 kPa)  
 160 kPa (0.2 l/s)  
 max. +70°C





[mpi.oras.com/1034F](http://mpi.oras.com/1034F)



## 1028F



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.21 l/s (300 kPa)  
 85 kPa (0.1 l/s)  
 max. +70°C



[mpi.oras.com/1028F](http://mpi.oras.com/1028F)

## 1029F



I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.19 l/s (300 kPa)  
 85 kPa (0.1 l/s)  
 max. +70°C



[mpi.oras.com/1029F](http://mpi.oras.com/1029F)

## 1027FS

I (ISO 3822)  
 EN 817  
 50 - 1000 kPa  
 0.14 l/s (300 kPa)  
 160 kPa (0.2 l/s)  
 max. +70°C



[mpi.oras.com/1027FS](http://mpi.oras.com/1027FS)



## 1030FS-104 , 1030FS-105

I (ISO 3822) Oras lab.


EN 817

50 - 1000 kPa

0.07 l/s (300 kPa w/Controller)(-104)

0.056 l/s (300 kPa w/Controller)(-105)

max. +80°C



[mpi.oras.com/1030FS-104](http://mpi.oras.com/1030FS-104)

## 1035FS-104 , 1035FS-105

I (ISO 3822) Oras lab.


EN 817

50 - 1000 kPa







0.056 l/s (300 kPa w/Controller)(-104)


0.07 l/s (300 kPa w/Controller)(-105)

max. +80°C



[mpi.oras.com/1035FS-104](http://mpi.oras.com/1035FS-104)




















1

max.  
1600 kPa






2















159670/10

159667/10













159670/10




159667/10











②



⑤









2.5  
A1











G1





G2



2.5  
G6





[cleaning.oras.com](http://cleaning.oras.com)



Oras Group is a powerful European provider of sanitary fittings: the market leader in the Nordics and a leading company in Continental Europe. The company's mission is to make the use of water easy and sustainable and its vision is to become the European leader of advanced sanitary fittings. Oras Group has two strong brands: Oras and Hansa.

The Group's head office is located in Rauma, Finland, and the Group has three manufacturing sites: Kralovice (Czech Republic), Olesno (Poland) and Rauma (Finland). Oras Group employs approximately 1,200 people in twenty countries. Oras Group is owned by Oras Invest, a family company and an industrial owner.

ORAS Ltd  
Isometsäntie 2, P.O. Box 40  
FI-26101 Rauma  
Tel. +358 2 83 161  
Fax +358 2 831 6300  
info.finland@oras.com  
www.oras.com



943426-02-22